ABSTRACT

A method of treating and completing a well includes positioning a downhole tool within a well. The downhole tool includes an elongated body defining a central passageway and including a plurality of production openings and at least one frac opening, a frac mandrel disposed within the central passageway, and a packer disposed about the elongated body. The method further includes securing the downhole tool in the well by the packer, fracing a formation through the frac opening, and producing a fluid from the formation through the production openings.